

SDMS US EPA REGION V -1

**SOME IMAGES WITHIN THIS
DOCUMENT MAY BE ILLEGIBLE
DUE TO BAD SOURCE
DOCUMENTS.**

Please type or print in ink. If you need additional space, use separate sheets of paper. Indicate the letter of the item which applies.

State Missouri Zip Code 63177

City Sauget County St. Clair State Illinois Zip Code 62201

Phone (314) 622-1400

From (Year) Unknown To (Year) 1957

[illegible]

EPA/CEPRO COPPER/EIL/PCB ATTORNEY WORK PRODUCT / ATTORNEY CLIENT PRIVILEGE

Waste Quantity

Place an X in the appropriate boxes to indicate the facility types found at the site.

In the "total facility waste amount" space give the estimated combined quantity (volume) of hazardous wastes at the site using cubic feet or gallons.

In the "total facility area" space, give the estimated area size which the facilities occupy using square feet or acres.

Facility Type

1. ☐ Piles
2. ☐ Land Treatment
3. ☒ Landfill
4. ☐ Tanks
5. ☐ Impoundment
6. ☐ Underground Injection
7. ☐ Drums, Above Ground
8. ☒ Drums, Below Ground
9. ☐ Other (Specify) _____

Total Facility Waste Amount

cubic feet 356,000

gallons

Total Facility Area

square feet

acres Unknown

G Known, Suspected or Likely Releases to the Environment:

Place an X in the appropriate boxes to indicate any known, suspected, or likely releases of wastes to the environment.

☐ Known ☐ Suspected ☐ Likely ☐ Not
☒ Do not know

Note: Items Hand I are optional. Completing these items will assist EPA and State and local governments in locating and assessing hazardous waste sites. Although completing the items is not required, you are encouraged to do so.

H Sketch Map of Site Location: (Optional)

Sketch a map showing streets, highways, routes or other prominent landmarks near the site. Place an X on the map to indicate the site location. Draw an arrow showing the direction north. You may substitute a publishing map showing the site location.

I Description of Site: (Optional)

Describe the history and present conditions of the site. Give directions to the site and describe any nearby wells, springs, lakes, or housing. Include such information as how waste was disposed and where the waste came from. Provide any other information or comments which may help describe the site conditions.

MCO 6580184

J Signature and Title:

The person or authorized representative (such as plant managers, superintendents, trustees or attorneys) of persons required to notify must sign the form and provide a mailing address (if different than address in item A). For other persons providing notification, the signature is optional. Check the boxes which best describe the relationship to the site of the person required to notify. If you are not required to notify, check ☐ EPA/CERCLA/COPPER/EIL/PCB ATTORNEY WORK PRODUCT / ATTORNEY CLIENT PRIVILEGE

Name George F. Knollmeyer, Plant Manager

Street: _____

City _____

State _____

Zip Code _____

Signature _____

Date 5/18/81

- JD+**
- ☐ Owner, Present
 - ☐ Owner, Past
 - ☒ Transporter
 - ☐ Operator, Present
 - ☐ Operator, Past
 - ☐ Other

EPA/CERCLA/COPPER/EIL/PCB ATTORNEY WORK PRODUCT / ATTORNEY CLIENT PRIVILEGE

CONFIDENTIAL
6/15/79

CONVERSATIONS ON WASTE DISPOSAL SITE SURVEY

Jack Vavind

[REDACTED]

Ray Walter

1. STATED HAULING WASTES FROM JFQ full time in 1958.
2. From late 40's to 1958 helped his Gravofater, Oscar F. Walter haul from plant

[REDACTED]

4. 1950-1957 hauled to a site near Sausal City Hall, EAST AND SOUTH OF WCK PLANT

[REDACTED]

MCO 6580185

HAROLD PAYNE

1. REMEMBERED JFQ HAULING WASTE IN EARLY 1950's
[REDACTED]. Then switching
to W GK landfill west of W GK plant.
 2. SAID HE HELPED hnd maleic or phthalic converters
to W GK landfill.
- [REDACTED]
- [REDACTED]
- [REDACTED]
- [REDACTED]

JACK BALTZELL

1. SAID WE USED [REDACTED]
[REDACTED] IN EARLY 1950s.
 2. HAULING [REDACTED] IN MID TO LATE
1950s
 3. USED W GK landfill extensively
- [REDACTED]
- [REDACTED]
- [REDACTED]
- [REDACTED]
- [REDACTED]
- [REDACTED]
- [REDACTED]
- [REDACTED]
- [REDACTED]
- [REDACTED]
- [REDACTED]

MCO 6580186